

Cybox Jungle Gym Cable Crossover 17090 Incorrect Cable Routing

Cybox has received reports of incorrect cable routing during installation on the Jungle Gym Cable Crossover Stations, model 17090. Incorrect routing of the cable can result in serious injury and poor operation. Premature wear may result if the cable is not routed correctly. To avoid injury, poor operation, and/or excessive wear; verify cables are routed correctly per the diagram below and ensure no interference from other components exist. Model 17091 was released in December 2010 with provisions to prevent misrouting the cable.

