

PRODUCT INFORMATION

Volume 2

June 2014

Revised Benches



Availability: Beginning the week of July 14th.

All orders in house shipping at that time will be fulfilled with the new versions.

Product Numbers:

- -10 to 80 Bench: 16000 becomes 16001
- Utility Bench: 16030 becomes 16031
- Flat Bench: 16040 becomes 16041

List Prices

No Changes

Improvements

- All of the benches have been redesigned so that there are no end caps.
- Contact with the floor is by a footpad and all floor level tubes are well above the floor to insure that a high point in an uneven floor cannot cause the bench to rock.
- The -10 to 80 Bench utilizes a completely redesigned seat pivot assembly. The pivot points are spaced nearly double the width and the pivot points themselves use hardened steel bushings. This combination minimizes the "slop" that accumulates through wear as well as the overall ability for movement.
- The -10 to 80 Bench now utilizes aluminum trim rather than the rubber end plugs. The aluminum trim rings are slick and more forgiving to having shoes drawn across them. Further, additional anchoring is included in the foot bar to keep the trim rings anchored.